

Replacement Sheet

Enter
C.C.
2/12/04




FIG. 2A








FIG. 2B







Replacement Sheet







Replacement Sheet



Replacement Sheet





Replacement Sheet

FIG. 6C






FIG. 6D



Replacement Sheet





Replacement Sheet

FIG. 8A





FIG. 8B



Replacement Sheet





FIG. 9A




FIG. 9B

Replacement Sheet




FIG. 10A




FIG. 10B

Replacement Sheet




FIG. 10C




FIG. 10D





FIG. 10E



Replacement Sheet




FIG. 11A




FIG. 11B

Replacement Sheet





FIG. 12A




FIG. 12B





FIG. 13A





FIG. 13B



Replacement Sheet

FIG. 14A







FIG. 14B






Annotated Sheet Showing Changes


FIG. 2A



Straighten lead line.

FIG. 2B





Annotated Sheet Showing Changes

FIG. 2C






FIG. 2D



128

FIG. 2E





Annotated Sheet Showing Changes

FIG. 2F




FIG. 2G






FIG. 2H



Annotated Sheet Showing Changes



Annotated Sheet Showing Changes




FIG. 6C







FIG. 6D






Annotated Sheet Showing Changes



Add reference character



Annotated Sheet Showing Changes




FIG. 8A








FIG. 8B



Annotated Sheet Showing Changes






Annotated Sheet Showing Changes



FIG. 10C




Show adhesive 154 between metal trace 144 and pad 116

Add reference character




FIG. 10D



FIG. 10E



Annotated Sheet Showing Changes






FIG. 12A




FIG. 12B





FIG. 13A




FIG. 13B

Show metal base 120



Annotated Sheet Showing Changes

FIG. 14A




FIG. 14B

